

March 3, 2021

Ms. Patricia Omondi Senior Construction Adviser/Special Projects Administrator **Redevelopment Authority of Prince Georges County -**9200 Basil Court - Suite 504 Largo, MD 20774

Re: Universal Hazardous Waste Inspection 4775 Town Square Boulevard Suitland, MD 20746

One Source Environmental Project Number: 21-1040A-HAZ

Dear Ms. Omondi:

#### INTRODUCTION

On February 17<sup>th</sup> and 18<sup>th</sup>, 2021, One Source Environmental, LLC (OSE) performed a visual inspection for Universal Hazardous Waste Materials at the referenced site. The work was performed prior to planned demolition activities at the site.

#### **METHODOLOGY**

The inspection was performed by Dharam Kissoondath who has completed HAZWOPER training in accordance with 29 CFR 1910.120. Representative machine, light fixtures, signs, and other potential hazards were visually assessed and inventoried during the inspection.

#### **FINDINGS**

The following potential environmental hazardous materials were identified in the building that will require special disposal handling prior to demolition activities:

- Freon Containing Air Conditioning Units and Refrigerator
- Chemical Containing Fire Extinguishers and 5 Gallon Buckets of Maintenance Items
- Mercury Containing Thermostat Switches
- Possible Oil Containing Heating Units
- Battery and Mercury Containing Exit and Emergency Lights
- Asbestos Containing Materials (ACM)
- Lead-based Paint (LBP) and Lead Containing Components
- Possible Biological Hazards from Human/Animal Excrement and Dead Rodents

A detailed spreadsheet inventorying Hazardous Materials is attached. See also accompanying Asbestos Inspection Report and Lead Screening Inspection Report.



#### **CONCLUSIONS AND RECOMMENDATIONS**

Any environmental hazardous waste containing materials should be reused for their intended purpose, recycled, or should be properly disposed of in a hazardous waste landfill. A certified Hazardous Waste Hauler should determine proper disposal of any of the above referenced items.

#### Respiratory protection should be donned at all times when working in the building.

Attached please find a detailed Spreadsheet Inventorying Hazardous Materials, Photographs, as well as our Inspector's Accreditation. OSE appreciates your interest in our services. If you have any questions, or if we can be of further assistance, please do not hesitate to contact me at (240) 286-2601.

Very truly yours,

One Source Environmental, LLC

William R. Ciancaglini

Project Manager bill@ose-llc.com

## Hazardous Material Inventory - 4775 Towne Square Blvd - Suitland, MD 20746

Space	AC Units	Heating Units	Fire Exting.	Mercury Switches	_	Exit Lights	Strobe Lights	Chemical 5 Gallon	Other
4775	29	15	4	2	1	5	4	6	See below
SPACE TOTALS	29	15	4	2	1	5	4	6	

## Other

Asbestos Containing Materials (ACM) - See Accompanying Asbestos Inspection Report
Lead-based Paint (LBP)/Lead Components - See Accopanying Lead Screening Inspection Report
Biological Contamination and General Trash Throughout - Human/Animal Excrement & Dead Rodents



# **Photographs**

Project No.: 21-1040A-HAZ Project Name: 4775 Towne Square Blvd – Suitland, MD



Photo Front of Site

#1:



Photo Site Address

#2:



Photo Non Mercury Thermostats #3: Throughout Building



Photo Non Mercury Thermostats #4: Throughout Building



Photo Electric Meter Room #5: 5 Gallon Buckets of Paint



Photo Fire Extinguishers #6: Hallways on Each Floor



# **Photographs**

Project No.: 21-1040A-HAZ

## Project Name: 4775 Towne Square Blvd – Suitland, MD



Photo Emergency Exit Lighting #7: Hallways



Photo Electric Meter Room #9: 5 Gallon of Roofing Sealant



Photo Fire Strobe Lights #8: Hallways on Every Floor



Photo Refrigerator #10: Laundry Area



Photo Mercury Thermostat #11: Some Units

# **AEROSOL MONITORING & ANALYSIS, INC.**

This is to certify that

DHARAM KISSOONDATH

has met the attendance requirements and successfully completed the course entitled

8-HOUR HAZWOPER REFRESHER -29 CFR 1910.120

| O8/28/2020 | O8/28/2020 | O8/28/2021 | STEVE SIERACKI | OR Principal Instructor | OR Principal

1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com